



**CHAMPION
ROOFING**

405.841.7663

OK# 80003787

INSPECTION REPORT

At Champion Roofing, we strive to deliver the best possible experience to homeowners and businesses alike. We combine quality materials, decades of industry expertise, and a passionate pursuit of excellence to provide truly exceptional service.

CHAMPIONROOFINGOK.COM



Job Name:
Task: [Flex Uploader](#)
Job Address:

Report Date: 05/07/2026

Inspection Report

Property Information

Job Name

Job Type
Residential

Phone Number
N/A

Email Address
N/A

About This Report

Report Created
05/07/2026

Assets
10

 Added Photos
5

 Annotations
0

 Images With Confirmed Damage
4

General Information

Completed by
Champion Roofing

Completed on
05/07/2026

Inspect List Type
N/A




AT007

Photo Added by Champion Roofing on
05/07/2026 4:15 PM CDT

Additional Notes

Champion Roofing
05/07/2026 4:21 PM CDT
During my inspection, I found very little hail damage to the roof. There was some cosmetic damage to the vents, but overall the roof is in good condition. The roof looks like it should have no issues passing insurance inspections.



AT021

Photo Added by Champion Roofing on
05/07/2026 4:19 PM CDT

Additional Notes

Champion Roofing
05/07/2026 4:19 PM CDT
Our hail map shows .75" hail at this address on March 10th 2026. This size of hail rarely damaged a newer shingle.









CONFIRMED DAMAGE

Hail Hit

1

 AT015

CLOSE UP EXAMPLES



NOTE






CONFIRMED DAMAGE

Hail Hit


1

 AT013

CLOSE UP EXAMPLES



NOTE






CONFIRMED DAMAGE

Hail Hit


2

AT014

CLOSE UP EXAMPLES



NOTE




CONFIRMED DAMAGE

Soft Metal Damage


7

AT016

CLOSE UP EXAMPLES



NOTE





AT003

Photo Added by Champion Roofing on
05/07/2026 4:13 PM CDT

Additional Notes

Champion Roofing
05/07/2026 4:13 PM CDT
Granule retention looks good.




AT002

Photo Added by Champion Roofing on
05/07/2026 4:16 PM CDT

Additional Notes


Champion Roofing
05/07/2026 4:16 PM CDT
No damage to the downspouts





Job Name:
Task: [Flex Uploader](#)
Job Address:

Report Date: 05/07/2026



AT001

Photo Added by Champion Roofing on
05/07/2026 4:16 PM CDT

Additional Notes

Champion Roofing
05/07/2026 4:16 PM CDT
No damage to the gutter

